

# Temperature and Humidity sensor



Download  
Catalogue



High precision measurement data



LCD screen display



Temperature Unit Switch



Humidity Measure Range: 0% RH~99% RHy



Temperature measuring range  
-20°C to 70°C

- Developed innovative equipment to ensure the easy and safe handling of corrosive reagents